

IECEX Quality Assessment Report: US/UL/QAR06.0010/03 details

! Fields marked with a star (*) are mandatory

QAR :

QAR Reference Number *: (automatic numbering)	US/UL/QAR06.0010/03		
Related QARs:	US/UL/QAR06.0010/07 US/UL/QAR06.0010/06 US/UL/QAR06.0010/05 US/UL/QAR06.0010/04 US/UL/QAR06.0010/02 US/UL/QAR06.0010/01 US/UL/QAR06.0010/00		
Status*:	Issued		
QAR Free Reference Number*:	UL QAR 10.10NK13563		
Audit Date* (yyyy-mm-dd):	2010-09-28		
Date of Issue* (yyyy-mm-dd):	2010-11-04		
Details of change*:	Reassessment Audit		
Valid until* (yyyy-mm-dd):	2013-09-28		
Site(s) audited*:	Otto Communications, Div. of Otto Engineering Inc. 2 East Main Street Carpentersville, IL 60110 USA		
Issuing ExCB*:	UL - Underwriters Laboratories Inc (UL)		
Manufacturer*:	Otto Communications, Div. of Otto Engineering Inc. 2 East Main Street Carpentersville, IL 60110		
Country of Manufacture*:	United States of America		
Product information*:	Audio Accessories		
Protection concept*:	Intrinsically Safe "ia"		
Related IECEX Certificates: (automatic linking)			
Related Certificates: (manual insertion)			
Related IECEX Certificates for previous versions:	ExCB	CoC and Status	Totals
	FMG	IECEX FMG 14.0030 issue: 0 [Current] IECEX FMG 14.0030 issue: 1 [Current] IECEX FMG 15.0018X issue: 0 [Current]	3
	UL	IECEX UL 06.0008X issue: 1 [Current] IECEX UL 06.0008X issue: 2 [Current] IECEX UL 06.0009X issue: 1 [Current] IECEX UL 09.0022X issue: 0 [Current] IECEX UL 09.0022X issue: 1 [Current] IECEX UL 09.0022X issue: 2 [Current] IECEX UL 09.0022X issue: 3 [Current]	7
			10
Comment:			
Attachment:			